Mace Boulevard




What we Heard...

- Congestion and frustration due to reduction from four travel lanes to two.
- Mace/Cowell intersection bulb-outs and pedestrian/bike area is too large.
- Crosswalks too wide and set back, impacts line of sight.
- Protected bike lane eliminates second travel lane, confines bikes, and is too wide.
- Difficulty exiting San Marino onto Mace due to congestion.
- Traffic lane width feels tight.




Solution Options

- San Marino Drive: Convert to stopcontrolled intersection, design revisions.
 Put HAWK signal in flashing red.
- El Macero to San Marino: Restore NB to two lanes.
- Cowell to El Macero: Restore to four lanes, remove protected bike lanes, restore bike lane(s) and/or construct multi-use path.
- Mace & Cowell: Reconstruct interior islands for easier turning.




Mace between Red Bud Dr. & San Marino Dr.


(no proposed changes)




To San Marino Dr




San Marino Dr. Intersection Design




= Existing project construction.




San Marino Dr. Alternative 1



San Marino Dr. Alternative 2





Mace Blvd. Between San Marino Dr. and El Macero Dr. Design




= Existing project construction.


Mace Blvd Between San Marino Dr. and El Macero Dr. Alternative






Mace Blvd. / El Macero Dr. Intersection Design







Mace Blvd. / El Macero Dr. Intersection Design: Alternative 1




Mace Blvd. / El Macero Dr. Intersection Design: Alternative 2




Mace Blvd. / Cowell Blvd. Intersection Design



Mace Blvd. / Cowell Blvd. Intersection Design: Alternative 1



Mace Blvd. / Cowell Blvd. Intersection Design: Alternative 2



End

cityofdavis.org/maceblvd